


Commercial Inspections




Sealing and finish issues

Basketball Court



Debris in finish



Buckling at granite entry

High end Designer shop




Gaps in planks



Lippage

Entry to high rise



Warpage



Seam issues

Steak House



Seams gapping



Moisture attacking adhesive, alkali salts

Medical Center



Debris under VCT




Maintenance Issues


Church



Stains on carpet



Seam gapping



Offices in Plant

Fibers crushing in traffic areas



Side match issues



Church

Side match issues



Side match issue



Night Club

Fraying at seams